Each

Dart Aerospace Ltd. Wednesday, 12/11/2008 1:38:07 PM Julie Dawson User: **Process Sheet** : COMFORT SEAT- FRAME **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 43359 **Estimate Number** : 13369 Part Number : D37521 P.O. Number · D3752 : 12/11/2008 S.O. No. : **Drawing Number** This Issue **Project Number** : N/A : NC Prsht Rev. : C : THERMOFORMING : // Type **Drawing Revision** First Issue : 43358 Material Previous Run : 08/12/2008 Qty: 1 Um: **Due Date** Written By Checked & Approved By 08.06.03 DL verified by:DD Comment New Issue Est Rev. B Dwg. Update 08/07/22 DL Est. Rev. C Dwg. Update Shorter length 08/10/28 DL Additional Product Job Number: Description: Seq. #: Machine Or Operation: HAND FINISHING THERMOFORMING HAND FINISH TH 1.0 Comment: HAND FINISHING THERMOFORMING Set up machine program D3752-1 Set up clamping frame as per folio MLEXS125F6002904 GE PLASTICS LEXAN SHEET 2.0 10.6670 sf(s) Comment: Qty.: 10.6670 sf(s)/Unit Total: GE PLASTICS LEXAN SHEET 3.0 Comment: HAND FINISHING THERMOFORMING 1) Cut Blanks

THERMOFORMING 4.0

Comment: THERMOFORMING MACHINE

Thermoform as per Dwg. D3752 and Folio

Dwg. Rev. ___ Folio Rev. ___

Dart Ae	rospace	e Ltd										
W/O:			V	ORK ORDER CHANG	ES							
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
. 			۲									
Part No:		PAR #:	Fault Category: No			NCR: Yes No DQA: Date:						
	÷.∕R	esolution:	Disposit	ion:	_ QA: N/C C	losed:		Date: _				
NCR:		V	VORK OR	DER NON-CONFORMA	NCE (NC	R)						
DATE	OTED	Description of NC	Corrective Action Section B			Verificat		n Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector			
				•								
		·				-						
						,						
								:				

NOTE: Date & initial all entries

Date: ` Wednesday, 12/11/2008 1:38:07 PM Julie Dawson .!Jser: **Process Sheet** Drawing Name: COMFORT SEAT- FRAME Customer: CU-DAR001 Dart Helicopters Services Part Number: D37521 Job Number: 43359 Job Number: Seq. #: Description: Machine Or Operation: INSPECT PARTS AS THEY COME OFF MACHINE 5.0 QC2 PARTS AS THEY COME OFF MACHINE HAND FINISHING THERMOFORMING HAND FINISH TH 6.0 Comment: HAND FINISHING THERMOFORMING 1) Trim to Finished Dimensions 7.0 QC2 Comment: INSPECT TRIMMED PARTS 1) Check dimensions to ensure conformity to drawing tolerances. INSPECT WORK TO CURRENT STEP 8.0 QC5 40 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 PACKAGING 1 9.0 Comment: PACKAGING RESOURCE #1 FINAL INSPECTION/W/O RELEASE 10.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion


Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			

Part No:		PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
DATE		Description of NC	Corrective Action Section B					Ammunual				
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector				
						P						
							}					

NOTE: Date & initial all entries



WORK ORDER:	43359
Part Number:	D3752-
	Page 1 of 1
	Part Number:

FIRST ARTICLE INSPECTION CHECKLIST

First Article Prototype

(Step 4) Thermoforming Visual Inspection Sign-off

Initial Initial
V
し に は に に に に に に に に に に に に に

(Step 6) Trimming FAI Checklist

Inspect dimensions highlighted on inspection sheet drawing _____Rev. __ and record below

Tolerance	Actual	Accept	Reject	Method of	Comm ents
	Dimension			Inspection	<u>(1)</u>
<u> </u>					(P)
MIN	.050				Mi Li
MIN		/			
MIN		~			M to the
MIN		V			MI CHI
MIN		/			加纳剂
MIN					44-67
	. 284	1			
					W. W.
	MIN MIN MIN MIN MIN	Dimension	Dimension	Dimension	Dimension Inspection

								1 1	14	467
Measur	ed by: 15h		Audited by:	8		Prototype Approval:	1			1.6
	Date: 08	11/12	Date:	128 hili	7	Date:		A		
		1937			/ -					1
Rev	Date	Change				Revised by	Ap	prov	ēd.	1
		New Issue								8
		1.15.1.10000								- 4